



1/8" shear  
pin  
prevents  
sprocket  
from  
lateral  
movement  
on the  
spindle.



Retaining ring  
prevents spindle  
assembly from sliding  
laterally.



Bronze oil impregnated  
thrust bushing with  
1/2" ID,  
Bronze oil impregnated  
flange bushing with  
1/2" ID, 3/4" OD.

Spindle Assembly

4/12/02

Clobberbots

Joseph P. Fleber  
4069 South Packard Avenue, St. Francis, WI 53235  
414-482-8905